

ENGLISH TRANSLATION
(Original in Punjabi)


OFFICE: EXECUTIVE ENGINEER, PROVINCIAL DIVISION, PUBLIC
CONSTRUCTION DEPARTMENT B & R BRANCH, MANSA
Telephone/Fax No.01652-2321189

Email ID : xen.mansa@gmail.com
Dated 08.02.22

Letter No.4060

To

Principal,
S.Chetan Singh Sarvhitkari
Sr. Sec. Vidya Mandir,
Mansa.



Sub: Regarding issuance of Building Safety Certificate
for the year 2022-23.

Ref: Yours' reference No. SVM/305/2021-22 dated 19/01/2022.

Your school building was inspected by the Sub Divisional Engineer. During inspection, it was found that the school building is safe. But Fire Safety Certificate has been issued by you till 19.05.2022. Therefore, keeping in view of the recommendation made by the Sub Divisional Engineer, School Building Fire Safety Certificate is issued till 19.05.2022. It is also clarified here that in case Fire Safety Certificate is got renewed by you till 31.03.2023, then validity of Building Safety Certificate be treated till 31.03.2023 and due to any reason, Fire Safety Certificate is not issued by the concerned department, then the validity of Building Safety Certificate be treated till 19.05.2022.

Encl: /Certificate and Site plan.

Sd/-
Executive Engineer,
Provincial Division PWD, B & R,
Mansa.

Endst.No.


Dated

A copy of the above is sent to Sub Divisional Engineer, Provincial Sub Division No.1, Mansa regarding his/her letter no.679 dated 03.02.2022 that keeping in view of your recommendation, Building Safety Certificate is issued to School.

Sd/-
Executive Engineer,
Provincial Division B & R Branch,
Mansa.


Certified to be True, Correct & Faithful
Translation in to the ENGLISH of The
Original in PUNJABI, (NOTARY PUBLIC)

Round Seal of
S.Chetan Singh
SVM Mansa
Receipt No.3481/22/21-22
Dated 09.02.22



PROFORMA FOR THE SAFETY OF SCHOOL BUILDING

1. Name of The School : Sardar Chetan Singh Sarvhitkari Sr.Sec.
Vidya Mandir,
2. Location : Jagdambe Road, Mansa
3. Plot Area : 94807.98 Sqft or 2.1765 Acres
4. Plinth Area : GF-27765.49 sqft 1st Fl.-26187.63 Sqft
2nd Floor-17727 Sqft
Total=71679 Sqft
5. No. of Storeys : 3
6. Year of Construction of Building : 1982-2021
7. If the Building has been Constructed under the supervision Of the qualified engineer, the following Details may be given : No
 - a) Name of the Engineer with qualification :-NA
 - b) Address of the engineer :-NA
 - c) Set of Structural drawings used in the Construction, if available
 - d) Name & Address of Architect with qualification :NA
8. Whether the building has been constructed for The purpose of
 - a) School Yes
 - b) Residential Purpose & Converted for use as School
9. Materials used for roofs
 - a) RCC Slabs RCC Slabs
 - b) R.S.Joists And Beams
 - c) Wooden Joist & Battens
 - d) Arch (Brick)
10. Materials used for Walls :
 - a) Mud Mortar
 - b) Cement Sand Mortar Cement Sand Mortar
11. Plaster:
 - a) Lime Mortar
 - b) Cement Mortar Cement Sand Mortar
12. Flooring
 - a) Conglomerate Tiles+ Conglomerate
 - b) Terrazo
 - c) Brick Paving
13. A detailed drawing indicating dimensions of rooms Attached Along with size and location of Doors/ Windows


Principal
S. Chetan Singh Sarvhitkari Sr. Sec.
Vidya Mandir, MANSA
(Affl. to C.B.S.E.) Aff. No. 1630927
School Code 20916

Building Safety Report

Name Of Building : Sardar Chetan Singh Sarvhitkari Senior Secondary Vidya Mandir" Mansa



(District- Mansa)

As per report of Ved Parkash Roy Assistant/ Junior Engineer on his visual inspection, the above mentioned school seems visually safe subject to the following observations and conditions:



1. The Parameters to check the stability and safety of building such as structural design, Architectural Drawings, Bearing Capacity, Foundation details, Structural Drawings, Technical specifications, Test reports of material used and quality control reports are not available.
2. In case any addition, alteration, expansion and modification to this building are required/ to be done, regarding this, inspection of undersigned may be arranged and obtained a certification after the completion from the undersigned
3. In case of building is affected by flood or if there is any settlement of walls foundation or roof etc. immediately inspection of undersigned arranged to check the stability and safety of the building.
4. A separate certificate regarding fire Fighting should be obtained from the competent authority
5. A separate certificate regarding Electrical Works should be obtained from the competent Authority
6. The owner of the Building/ Management is fully responsible regarding safety of the Building from all angles in spite of this report
7. This report is for the covered area of the Building 71679(GF-Sqft, which is submitted by the owner of the school building as per drawing
8. This report is not valid for legal purpose
9. That the fee charges for the year 2022-23

As per Visually inspection as reported by the concerned Assistant/ Junior Engineer the above building may be used for normal use for one year upto 19-05-2022 ~~31-03-2023~~ subject to the above condition.


Assistant/ Junior Engineer


Sub Divisional Engineer,
Provl. Sub Divn. No.1 PWD (B&R)
Mansa 

COVERED CORRIDOR 12X105





Sub Divisional Engineer,
Prov. Sub Divn. No.1 PWD (B&R)
Manisa

Er. Bhagat Bhushan Bans
Architect, Engineer & Valuer
Approved by M.C., MANISA
Vide Order No. 409, Dt. 06-01-17

GROUND FLOOR PLAN

S. Chetan Singh Sarvhitkar
Principal
Vidya Mandir, MANISA
(Aff. to C.B.S.E.) Aff. No. 1630927
School Code 20916



Sketch prepared by me @ 24

Sub Divisional Engineer,
 Prof. Sub Divn. No. 1 PWD (B&R)
 Mansa

Sub Divisional Engineer,
 Provl. Sub Divn. No. 1 PWD (B&R)
 Mansa

S. Chetan Singh Sarvhitkar
 Principal

Er. Bhavrat Bhushan Bans
 Architect, Engineer & Valuer
 Approved by M.C., MANS
 Vide Order No. 489, Dt. 06-01-19

S. Chetan Singh Sarvhitkar Sr. Sec.
 Vidya Mandir, MANS
 (Aff. to C.B.S.E.) Aff. No. 1630927
 School Code 20916

IST FLOOR PLAN

BUILDING OF Sardar Chetan Singh Sarv Hitkari Sr. Secondary School, Vidya Mandir AT JAGDAMBE ROAD, MANSA]




VIDYA BHARTI EDUCATIONAL TRUST

Specification's

1. Spread Footing Foundation With Base Conc. 1:8:16
2. B/W in Foundation Up to Plinth in Lime Mortar
3. 1st Class With in Super Structure With C.S. Mortar 1:6
4. R.C.C./ R.B.C. Slab
5. C.S Plaster on Walls & Ceiling.
6. Tile Terracing
7. Wood Work / Iron Work In Joinery
8. Conglomerate Flooring 1:2:4
9. D.P.C. 1:2:4 In C.Con. With Two Coats of Hot Bitumen

Details of Joinery

Size	Sill Level	No.
D= 4'0" x 7'0"	0'0"	27+30+15
D1= 3'0" x 7'0"	0'0"	3+1+3
D2= 2'6" x 7'0"	0'0"	14+15+13
D3= 3'6" x 7'0"	0'0"	1
W= 4'9" x 4'0"	3'0"	19+29+7
W1= 4'0" x 4'0"	3'0"	48+44+20
W2= 5'0" x As Per Site		0+1+1
W3= 3'6" x 4'0"	2'6"	1
W4= 3'0" x 3'3"	3'9"	2
V= 3'0" x 3'0"	5'0"	4+3+2
V1= 1'6" x 1'6"	6'6"	16+16+10



Area Statement

Total Area OF Land=94807.98Sqft or 105345sqyd=2.1765 acre
 Ground Floor Covered Area =27764.49Sqft
 First Floor Covered =26187.63Sqft
 Second Floor Covered Area = 17727Sqft
 Total Covered Area=71679Sqft
 Play Ground Area= 51027Sqft

Sign. Of Owner

sign. Of Architect

2ND FLOOR PLAN

Stel inspected by me (W)

[Signature]
 Principal
 S. Chetan Singh Sarvhitkari Sr. Sec.
 Vidya Mandir, MANSA
 (Affi. to C.B.S.E.) Affi. No. 1630927
 School Code 20916

[Signature]
 Sub Divisional Engineer,
 Provl. Sub Divn. No.1 PWD (B&R)
 Mansa

[Signature]
Er. Bhurat Bhushan Bansal
 Architect, Engineer & Valuer
 Approved by M.C., MANSA
 Vide Order No. 489, Dt. 06-01-1986